

Clarvon Veris

Hardware Setup Guide

Simple step-by-step instructions for tripod setup, case mounting, power, and airflow.



QUICK OVERVIEW



1.

Set Up
the Tripod



2.

Mount
the Case



3.

Connect
Power



4.

Check
Airflow

SEE IT. UNDERSTAND IT. TRUST IT.

1. Set Up the Tripod

1 Open the tripod legs

Spread all three legs fully on a flat, level surface.




2 Lock the base

Tighten the lower red knob to secure the legs.



3 Adjust height

Raise the center shaft to the desired height, then tighten the middle red knob.




Before moving on, make sure the tripod is stable and does not wobble.

2. Mount the Case & Connect Power

1 Align the case

Line up the mounting post on the bottom of the case with the tripod mount.



2 Lock it in place

Seat the case fully and make sure it is secure.



Use the red PUSH release only when removing the case.



3 Connect power

Open the case, connect the power bank to the Veris unit, and confirm the startup light turns on.



Keep cables neat and make sure nothing is pinched by the case.

3. Check Airflow & Final Setup

1 Keep vents clear

Do not block the vented sides of the Veris unit.




2 Leave the case open

Keep the lid open during testing so room air can circulate around the sensors.



3 Give it space

Leave open space around the unit. Do not press it against walls, curtains, or other objects.



Final Checklist

- ☐ Tripod stable
- ☐ Case secure
- ☐ Power connected

- ☐ Startup light on
- ☐ Vents clear
- ☐ Case open

i Accurate readings depend on good airflow.